









BNC Jack (PBT Housing), Fork Type

| | | | |
|---|---|------------|---------------------------|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |
| | | PCB Layout | Refer to S-CONN's Drawing |

BNC R/A Jack (PBT Housing)



| | | | |
|---|---|------------|---------------------------|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |
| | | PCB Layout | Refer to S-CONN's Drawing |

BNC R/A Jack (Metal Housing)



| | | | |
|---|--|------------|---------------------------|
|  |  | Hand Tool | See Appendix B |
| | | Cable | Nil |
| | | PCB Layout | Refer to S-CONN's Drawing |


Printed Circuit Board, Straight or R/A Terminal

BNC Jack (Metal Housing)



| | | | |
|---|--|------------|---------------------------|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |
| | | PCB Layout | Refer to S-CONN's Drawing |

BNC Jack, PCB Type



| | | | |
|---|---|------------|---------------------------|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |
| | | PCB Layout | Refer to S-CONN's Drawing |





BNC R/A Jack, PCB Type (75 ohm)

| | | | |
|---|---|------------|---------------------------|
|  |  | Hand Tool | See Appendix B |
| | | Cable | Nil |
| | | PCB Layout | Refer to S-CONN's Drawing |

BNC R/A Jack, PCB Type (75 ohm)



| | | | |
|---|---|------------|---------------------------|
|  |  | Hand Tool | See Appendix B |
| | | Cable | Nil |
| | | PCB Layout | Refer to S-CONN's Drawing |

BNC Bulkhead Jack



| | | | |
|---|---|------------|---------------------------|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |
| | | PCB Layout | Refer to S-CONN's Drawing |

Bulkhead Receptacle, Solder Pot Terminal

BNC Bulkhead Solder Plug



| | | | |
|---|---|---------------|---------------------------|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |
| | | Mounting Hole | Refer to S-CONN's Drawing |

BNC Chassis Mount Plug



| | | | |
|---|---|-----------|-----|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |





Bulkhead Receptacle, Solder Pot Terminal BNC Chassis Mount Jack

| | | | |
|---|---|---------------|---------------------------|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |
| | | Mounting Hole | Refer to S-CONN's Drawing |



BNC Bulkhead Jack, Isolated Type

| | | | |
|---|---|---------------|---------------------------|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |
| | | Mounting Hole | Refer to S-CONN's Drawing |

BNC Chassis Mount Jack-4 Hole



| | | | |
|---|---|---------------|---------------------------|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |
| | | Mounting Hole | Refer to S-CONN's Drawing |

BNC Bulkhead Jack

| | | | |
|---|---|---------------|---------------------------|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |
| | | Mounting Hole | Refer to S-CONN's Drawing |



Boots

BNC Boot



| | | | |
|---|---|----------------------------|--------------------|
|  |  | Hand Tool | Nil |
| | | Cable | RG58/U,59/U, 174/U |
| | | Cable Assembly Instruction | Nil |

Terminator & Cap



Protective Cap for BNC Jack

| | | | |
|---|---|-----------|-----|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |

BNC Plug Terminator w/ Chain 50R/75R/93R

| | | | |
|---|---|-----------|-----|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |

BNC Plug Terminator

| | | | |
|---|---|-----------|-----|
|  |  | Hand Tool | Nil |
| | | Cable | Nil |